	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition
1	BRS	L1	54643	power near5 (processor microprocessor cpu mpu) -		2005/03/21 20:36	• • .	
2	BRS	L2	31321	(stop\$4 sleep) same clock	US- PGPUB; USPAT	2005/03/21 20:37		
3	BRS	L3	10591	(low\$2 near5 power) same clock		2005/03/21 20:38		
4	BRS	L4	1228	1 same 2		2005/03/21 20:38		
5	BRS	L5	1307		US- PGPUB; USPAT	2005/03/21 20:38		
6	BRS	L6	1958	4 or 5	US- PGPUB; USPAT	2005/03/21 20:39		·
7	BRS	L7	440226		US- PGPUB; USPAT	2005/03/21 20:42	· ()	
8	BRS	L8	1100	6 and 7		2005/03/21 20:43		
9	BRS	L9	250834	(start\$3 wak\$3 initiat\$3) near5 process\$3		2005/03/21 20:45		
10	BRS	L10	518		US- PGPUB; USPAT	2005/03/21 20:49		
11	BRS	L11 -	- 513	10 and (state mode)	US- PGPUB; USPAT	2005/03/21 20:51		
12	BRS	L12	74604	clock near5 frequency		2005/03/21 20:51	_	
13	BRS	L13	284	11 and 12	US- PGPUB; USPAT	2005/03/21 20:52		
 14	BRS	 L14	2396	713/300-320.ccls.	US- PGPUB; USPAT	2005/03/21 20:52		
15	BRS	L15	1428	713/322-324.cds.	US- PGPUB; USPAT	2005/03/21 20:53		e op en 12 apperen endere

	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition
16	BRS	L16	333	713/601.ccls.	DIADI IK.	2005/03/21 20:53	-	·
17	BRS	L17	3553	14 or 15 or 16	US- PGPUB; USPAT	2005/03/21 20:54		
18	BRS	L18	105	13 and 17	DI-DI IR'	2005/03/21 20:54		